

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 12/20/2012	3. Time Prepared 1745
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief	6. Operational Period 0700, 12/19/2012 – 1720, 12/19/2012	
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Dan Zahner		Situation Unit	St. Louis, MO
8. Activity Log			
Time	Major Events		

0730	<p>River Status</p> <ul style="list-style-type: none"> • MP 5.00 to MP 5.25(C0.4 Boat Launch) RDB: Random streamers of sheen and tar globs observed. Not enough to warrant a sheen response. • MP 5.25 to MP 5.5 LDB: Random streamers of sheen and oil globules observed. Not enough to warrant a sheen response. • MP 5.60 to control point RDB: Few streamers of sheen and oil globules observed. Not enough to warrant a response. • MP 5.63 LDB: Few streamers of sheen and oil globules observed. Not enough to warrant a response. • MP 5.65 (Control Point): Few streamers of sheen and oil globules observed. Not enough to warrant a response. • MP 5.55 RDB (Former submerged oil location): Few sheen streamers and oil globules observed. Not enough to warrant a sheen response. • MP 8.50 L1: Not visited today. • MP 8.50 L2: Not visited today. • MP 8.75 R1: Not visited today. • MP 10.75 LDB: No sheen or oil globules observed. • MP 11.79 LDB: Not inspected today. • C5 Boat Launch (MP 15.00): No sheen or oil globules observed. • MP 15.00 (Mill Ponds): Few spots and streamers of sheen and oil globules observed in the South Mill Pond. Not enough to warrant a sheen response. • MP 21.50 RDB: No sheen or oil globules observed. • MP 23.15 RDB: Not visited today. • MP 24.75 LDB: Not visited today. • MP 26.00 RDB: No sheen or oil globules observed. • MP 26.25 RDB: No sheen or oil globules observed. • MP 28.25 RDB: No sheen or oil globules observed. Pom Poms remain in place from bathymetry crew. • MP 36.25 LDB: No sheen or oil globules observed. • MP 36.50 RDB: No sheen or oil globules observed. • Delta: No sheen observed. • Morrow Lake North Cove: Random spots of sheen and oil globules observed. Sheen response called in and sheen sweep was conducted. • Morrow Lake South Cove: Random streamers of sheen and oil globules observed. Not enough to warrant a sheen response. • Rowe Island: No sheen or oil globules observed.
1720	Return to ICP. End of field day.

9. Prepared by (Name and Position)

Dan Zahner, Situation Unit, USEPA-START